To: Goertz, Dave[Dave.Goertz@WestonSolutions.com]; Way, Steven[way.steven@epa.gov];

Myers, Craig[Myers.Craig@epa.gov]

Cc: Robinson, David[David.Robinson@WestonSolutions.com]

From: Petri, Elliott

Sent: Mon 10/19/2015 10:09:12 PM

Subject: RE: GKM - From the Mine to the Distribution Box

Forgot to include the link for the flow measurement device:

http://www.greyline.com/avfm50.htm

Elliott Petri, PE

Weston Solutions, Inc.

1435 Garrison St, Ste 100

Lakewood, CO 80215

Ph: 303-729-6156

Cell: 719-216-2754

Fax: 303-729-6101

From: Petri, Elliott

Sent: Monday, October 19, 2015 4:07 PM

To: Goertz, Dave <Dave.Goertz@WestonSolutions.com>; Way, Steven (way.steven@epa.gov)

<way.steven@epa.gov>; 'Myers.craig@Epa.gov' <Myers.craig@Epa.gov>

Cc: Robinson, David < David. Robinson @Weston Solutions.com >

Subject: GKM - From the Mine to the Distribution Box

Hi All,

I spoke with Steve today and I am hoping to get all of us on the same page with the Gold King Inlet structure, flow measuring device, and conveyance into the distribution manhole outside the mine.

1792323 ED_000792_00006458-00001

• • • • • • • • • • • • • • • • • • •
• • • • • • • • • • • • • • • • • • •
O I will look into the possibility of if telemetry is possible between this device and the in-situ equipment per Craig's request.
O Some thought will be put into how the measurement device is placed into the water for accessibility for maintenance or replacement, Dave Goertz is currently considering some options on that.
If there is anything else I am missing here please reply all so we can get this information shared and the drawings will encompass what is needed.
Thanks,
Elliott
Elliott Petri, PE
Weston Solutions, Inc.
1435 Garrison St, Ste 100
Lakewood, CO 80215
Ph: 303-729-6156

CONFIDENTIALITY: This email and attachments may contain information which is confidential and proprietary. Disclosure or use of any such confidential or proprietary

Cell: 719-216-2754

Fax: 303-729-6101

information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return e-mail and delete this email from your system. Thank you.